


























(S) Apply a small amount of Ord.No.10/24 thread lock when fixing a metal part.













(S)  Apply a small amount of Ord.No.10/24 thread lock when fixing a metal part.














(S)  Apply a small amount
of Ord.No.10/24
thread lock when fixing
a metal part.







(K) Ord.No.10/27
(S) Ord.No.10/24
(Sk) Ord.No.10/125

